



GREEN AUCTION

MANLIFT

LotNo	8263002	LOCATION	KOBE-N*
-------	---------	----------	---------

MAKER	MAEDA	YEAR	—				
MODEL	HF120-2	HOUR	4160	CARRIER HR	—	CARRIER KM	—
S/N	12HF2135	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—		
	MODEL	S3L2	—		MAIN WINCH	—	OUTRIGGER CYLINDER	—		
	S/N	120794K5	—		AUX WINCH	—	OUTRIGGER EXTENSION	—		
	COOLANT	OK	—		BOOM EXTENSION	OK	SWING	OK		
	OIL	OK	—		BOOM HOIST	OK	CONTROL LEVER	OK		
	START	OK	—		NOTE					
	BLOW-BY	NO / なし	—							
	NOISE	NO / なし	—							
	NOTE									
HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)	BOOM	LENGTH	12	m	
	NO. OF HOOK	— pcs					CONDITION	OK		
	WIRE ROPE	—					SHEEVE	OK		
	NOTE						NOTE			
TRANSMISSION	NO. OF SPEED	F	—	R	—	JIB	NO. OF SEC	—	sec	
	SHIFT	—					CONDITON	—		
	OIL	—					NOTE			
	NOTE									
CAB	SEAT	—				SAFETY DEVICE	MONITOR	OK		
	NOTE						AML	—		
							OVER WIND CUT	—		
							NOTE			
FORK LIFT	HYDRAULIC	TYPE	—			BRAKE	FOOT	OK		
		FORK	LENGTH	—	mm		PARKING	OK		
		MAST	LENGTH	—	mm		NOTE			
		LIFT CYLINDER	—							
TILT CYLINDER	—									
HOIST CYLINDER	—									
NOTE										
TIRE	UNDERCARRIAGE	SIZE	—			REMARK	*PUNCHED NO. UNKNOWN (刻印不明)			
		CONDITION	—							
		SHOE	W/PAD	TYPE	RUBBER					
		300 mm	OK							
PIN BUSH	OK									
CARRIER ROLLER	OK									
TRACK ROLLER	OK									
FRONT IDLER	OK									
SPROCKET	OK									
NOTE										

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました