



GREEN AUCTION

LotNo	1263020	LOCATION	HAKATA-S
-------	---------	----------	----------

MAKER	HITACHI	YEAR	2013
MODEL	ZX40U-5A	HOURL	-
S/N	30960		

MINI EXCAVATOR

163th Tender Auction 2026/09/03 ~ 2026/09/04

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	4TNV88-ZPHB	
	S/N	P1275	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	YES/あり(SLIGHTLY/小)	
	NOISE	NO/なし	
	EPA	NO/なし	
	NOTE		

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☒ W/PAD	OK	
	400 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	SHOE LINK PLAY. シューリンク ガタ DIRTY, REQUIRES CLEANING. 汚れあり 要洗車	

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK REINFORCED/補強あり	
	PIPING	OK	
	BUCKET	TYPE	STD
		OK	
	BLADE	DENT/へこみ	
	PINS	BOOM	LOOSE/ガタ
		ARM	LOOSE/ガタ
		BUCKET	LOOSE/ガタ(SEVERELY/大きい)
	NOTE		

CAB/CNP	CAB/CNP	ROOF DENTED. ルーフへこみ	
	ROPS	NO/なし	
	SEAT	TORN/破れ	
	CONTROL LEVER	OK	
	A/C OR HEATER	-	
	COMPUTER	NG	
	MONITOR	NG	
	BATTERY	OK	
	NOTE		

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	ROD SCRATCHED/ロッド傷あり
	BUCKET	OIL SEEPAGE /油にじみ
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

W/ MULTI LEVER

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました