



GREEN AUCTION

MINI EXCAVATOR

LotNo	1144004	LOCATION	KOBE-N*
MAKER	KUBOTA	YEAR	2007
MODEL	U-20-3S	HOURL	3156
S/N	10999		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1105
	S/N	7A7760
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	☐ W/PAD		
	250 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
			OK
	ARM	TYPE	STD
			OK
	PIPING	OK	
	BUCKET	TYPE	STD
			OK
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	TORN / 破れ
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	ARM SET TO LIMIT POSITION" DISPLAYED ON MONITOR/モニターに「制限位置にアームセット」の表示が出る

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK
NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP / 在来船輸出の場合は要洗車

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました