



GREEN AUCTION

EXCAVATOR

LotNo	2144001	LOCATION	KOBE-N*
MAKER	HITACHI	YEAR	2014
MODEL	ZX75US-3	HOURL	6997
S/N	64699		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	4LE2XCUIA
	S/N	4LE2-612845
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☐ W/PAD		
	450 mm	OK	
	PIN BUSH	WORN / 摩耗	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
			BOOM HAS WELDING MARKS/ブームに溶接跡あり
	ARM	TYPE	STD
			OK
	PIPING	OK	
	BUCKET	TYPE	-
			-
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE	WINCH INOPERABLE(MOTOR RUNNING)/ウインチ不動(モーター音はする) OIL LEAK FROM PIPING END(MISSING BLANKING CAP)/配管先端より油漏れ(めくらキャップ欠品の為)	

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OIL LEAK / オイル漏れ
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK
*PUNCHED NO. UNKNOWN (刻印不明)

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました