



GREEN AUCTION

FORKLIFT

LotNo	7144001	LOCATION	HAKATA-A*
-------	---------	----------	-----------

MAKER	KOMATSU	YEAR	2003				
MODEL	FD25C-15	HOUR	3374	CARRIER HR	—	CARRIER KM	—
S/N	575951	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER		CRANE		HYDRAULIC (CRANE)	PUMP	—		TYPE OF OUTRIGGER	—		ELECTRICAL	LIGHT	OK			
	MODEL	4D94E		—		MAIN WINCH	—		OUTRIGGER CYLINDER	—			WIPER	—			
	S/N	25270		—		AUX WINCH	—		OUTRIGGER EXTENSION	—			HEATER	—			
	COOLANT	—		—		BOOM EXTENSION	—		SWING	—			A/C	—			
	OIL	OK		—		BOOM HOIST	—		CONTROL LEVER	—			BATTERY	OK			
	START	OK		—		NOTE							NOTE				
	BLOW-BY	YES / あり		—													
	NOISE	NO / なし		—													
	NOTE	WHITE SMOKE / 白煙あり RADIATOR COVER CANNOT BE REMOVED. / ラジエーターカバー取り外し不可															
HOOK	CAPACITY	MAIN	— (t)		SUB	— (t)		BOOM	LENGTH	— m		FORK LIFT	TYPE	—			
	NO. OF HOOK	— pcs					CONDITION		—		FORK			LENGTH	1550 mm		
	WIRE LOUPE	—					SHEEVE		—					OK			
	NOTE						NOTE				MAST			LENGTH	3000 mm		
TRANSMISSION	NO. OF SPEED	F	—		R	—		JIB	NO. OF SEC	— sec		HYDRAULIC	LIFT CYLINDER	OK			
	SHIFT	—					CONDITON		—		TILT CYLINDER		OK				
	OIL	—					NOTE				HOIST CYLINDER		OK				
	NOTE										NOTE						
SAFETY DEVICE	CAB	—					MONITOR	—		BRAKE	FOOT	STUCK / 固着		REMARK	ENGINE RPM SURGES VIOLENTLY AFTER STARTING DUE TO A STUCK ACCELERATOR. / アクセル固着のため、始動後回転数激しい OVERALL CORRODED. / 全体的に腐食あり		
	SEAT	—						AML	—		PARKING	NOT WORKING. / 効かない					
	NOTE							OVER WIND CUT	—		NOTE						
								NOTE									

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました