



GREEN AUCTION

EXCAVATOR

LotNo	2264013	LOCATION	KOBE-N
MAKER	KOBELCO	YEAR	2014
MODEL	SK200-9	HOURL	7522
S/N	YN13-70744		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不動車

ENGINE	MODEL	J05E-TJ
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

UNDERCARRIAGE	SHOE ☐ W/PAD	TYPE	STEEL
	600 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	OK	
	BUCKET	TYPE	STD
		OK	
	BLADE	—	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	LOOSE / ガタ
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	YES / あり
	SEAT	WORN / 破れ
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	DEAD / あがり
	NOTE	ERROR CODE F033 DISPLAYED. / エラー「F033」表示 SIDE COVER RUST / サイドカバーサビ

CYLINDERS	BOOM	RH MINOR OIL LEAK / 右側オイルにじみ
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	—
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	—
------------	---

REMARK
2.9TON ARM CRANE / クレーン付き NEED WASHING / 要洗車

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました