



GREEN AUCTION

WHEEL LOADER

LotNo	3264002	LOCATION	HAKATA-A
MAKER	mitsubishi	YEAR	2000
MODEL	WS210	hour	8173
S/N	8W004580	MILE	—

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	K4F-E1
	S/N	K4F-47796
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES / あり
	NOISE	YES / あり
EPA	NO / なし	
	NOTE	

CABIN/CANOPY	CAB/CNP	—
	ROPS	—
	SEAT	TORN / 破れ
	NOTE	

ELECTRICAL	LIGHT	NG
	WIPER	—
	HEATER	—
	A/C	—
	BATTERY	DEAD / あがり
	NOTE	

HYDRAULIC	PUMP	OK
	LIFT CYLINDER	OK
	TILT CYLINDER	OK
	STEERING CYLINDER	MINOR OIL LEAK / オイルにじみ
	LINE	OK
	NOTE	

TRANSMISSION	GEAR	NOT TESTED / 未確認
	SHIFT	NOT TESTED / 未確認
	OIL	NOT TESTED / 未確認
	NOTE	

FRAME	MAIN FRAME	OK
	CENTER PIN	OK
	NOTE	RUSTY / サビ

TIRES	SIZE	12.5/8.0-18
	CONDITION	OK
	NOTE	TIRE DETACHMENT / タイヤ外れ

BRAKE & STEERING	FOOT BRAKE	NOT TESTED / 未確認
	PARKING BRAKE	NOT TESTED / 未確認
	STEERING OPERATION	NOT TESTED / 未確認
	NOTE	

DIFF.CASE(F)	OK
DIFF.CASE(R)	OK
COUNTER WEIGHT	OK

BUCKET LOADER	ARM	OK
	PINS	OK
	TYPE	STD
	SERIAL	—
	EDGE	OK
	TEETH	—
	GENERAL CONDITION	CRACK, CORRODED. / 亀裂 腐食
NOTE	PROPELLER SHAFT SPLINES SLIPPING OUT. / プロペラシャフトスプ ライン抜けかけ	

BLANK

REMARK

UNABLE TO DRIVE TO TIRE DETACHMENT. / タイヤ外れのため走行不可

NEED REPAIR. / 要修理

*NEED LIFT CHARGE FOR RELEASING. (別途リフトチャージ必要)

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました