



GREEN AUCTION

MINI EXCAVATOR

LotNo	1145017	LOCATION	YOKOHAMA-E
MAKER	KUBOTA	YEAR	2015
MODEL	RX-306	HOURL	4857
S/N	15659		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1703
	S/N	7EW8830
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	☐ W/PAD		
	300 mm	CRACK / 亀裂	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP / 在来船輸出の場合は要洗車	

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
			OK
	ARM	TYPE	STD
			OK
	PIPING		-
	BUCKET	TYPE	STD
			OK
	BLADE	PEEL BACK. / めくれ	
	PINS	BOOM	OK
		ARM	LOOSE / ガタ (SLIGHTLY/小)
		BUCKET	LOOSE / ガタ (SLIGHTLY/小)
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	TORN / 破れ
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	2WAY MULTI CONTROL LEVER. / 2WAY マルチレバー

ATTACHMENT	-
------------	---

REMARK
W/HOOK. / フック付き
CONTROL VALVE MINOR OIL LEAKING. / コントロールバルブオイルにじみ
ENGINE HOOD KEYHOLE MISSING. / エンジンフード鍵穴欠品

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました