GREEN AUCTION

EXCAVATOR

LotNo	2265010	LOCATION	HAKATA-S

MAKER	KOBELCO	YEAR	2013
MODEL	SK200-8	HOUR	6715
S/N	YN12-64328		

☐ DOCUMENT/書類　☐ UNABLE TO TRAVEL(START)/不動車

ENGINE

MODEL	J05E-TA
S/N	ー
COOLANT	OK
OIL	OK
START	OK
BLOW-BY	YES / あり(SLIGHTLY/小)
NOISE	NO / なし
EPA	NO / なし
NOTE	

UNDERCARRIAGE

SHOE ☐ W/PAD	TYPE	STEEL
600 mm	RUSTY, CORRODED. / サビ　腐食	
PIN BUSH	OK	
CARRIER ROLLER	OK	
TRACK ROLLER	OK	
FRONT IDLER	OK	
SPROCKET	OK	
NOTE		

FRONT ATTACHMENT

BOOM	TYPE	STD
	OK	
ARM	TYPE	STD
	OK	
PIPING	ー	
BUCKET	TYPE	STD
	OK	
BLADE	-	
PINS	BOOM	LOOSE / ガタ
	ARM	LOOSE / ガタ
	BUCKET	LOOSE / ガタ
NOTE		

CAB/CNP

CAB/CNP	OK
ROPS	NO / なし
SEAT	OK
CONTROL LEVER	-
A/C OR HEATER	DEFECT / 不良
COMPUTER	OK
MONITOR	OK
BATTERY	OK
NOTE	

CYLINDERS

BOOM	OK
SWING	OK
ARM	OK
BUCKET	OK
BLADE	-
NOTE	

TURN TABLE	OK

CONTROL

HYDRAULIC PUMP	OK
TRAVEL	OK
SWING	-
CONTROL	OK
NOTE	MULTI CONTROL LEVER. / マルチレバー

ATTACHMENT	ー

REMARK

2.9T ARM CRANE / クレーン付き

COVER RUSTY, SCRATCHED, / カバーサビ　傷
CORRODED SEVERELY. / 腐食多い

NEED WASHING. / 要洗車

ATTENTION/注意　*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました