GREEN AUCTION

EXCAVATOR

LotNo	2265013	LOCATION	HAKATA-A

MAKER	HITACHI	YEAR	2007
MODEL	ZX225US-3	HOUR	7951
S/N	206969		

☐ DOCUMENT/書類　☐ UNABLE TO TRAVEL(START)/不動車

ENGINE

MODEL	4HK-1
S/N	ー
COOLANT	OK
OIL	OK
START	OK
BLOW-BY	NO / なし
NOISE	NO / なし
EPA	NO / なし
NOTE	

UNDERCARRIAGE

SHOE ☐ W/PAD	TYPE	STEEL
600 mm	OK	
PIN BUSH	OK	
CARRIER ROLLER	OK	
TRACK ROLLER	OK	
FRONT IDLER	OK	
SPROCKET	OK	
NOTE		

FRONT ATTACHMENT

BOOM	TYPE	STD
	OK	
ARM	TYPE	STD
	OK	
PIPING	ー	
BUCKET	TYPE	SLOPE
	CRACK / 亀裂	
BLADE	-	
PINS	BOOM	OK
	ARM	OK
	BUCKET	LOOSE / ガタ
NOTE		

CAB/CNP

CAB/CNP	MISSING DOOR. / ドア欠損
ROPS	NO / なし
SEAT	OK
CONTROL LEVER	OK
A/C OR HEATER	OK
COMPUTER	OK
MONITOR	OK
BATTERY	OK
NOTE	

CYLINDERS

BOOM	OIL LEAKING SLIGHTLY / オイル漏れ小
SWING	-
ARM	OK
BUCKET	MINOR OIL LEAK / オイルにじみ
BLADE	-
NOTE	

TURN TABLE	OK

CONTROL

HYDRAULIC PUMP	OK
TRAVEL	OK
SWING	OK
CONTROL	OK
NOTE	CONTROL VALVE OIL LEAK. / コントロールバルブオイル漏れ

ATTACHMENT	ー

REMARK

SIDE COVER DENT. / サイドカバーへこみ

NEED WASHING. / 要洗車

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました