GREEN AUCTION

EXCAVATOR

LotNo	2265001	LOCATION	KOBE-N*

MAKER	KOMATSU	YEAR	2007
MODEL	PC78US-6	HOUR	9685
S/N	11785		

☐ DOCUMENT/書類　☐ UNABLE TO TRAVEL(START)/不動車

ENGINE

MODEL	S4D95LE-3-A
S/N	123775
COOLANT	OK
OIL	OK
START	OK
BLOW-BY	NO / なし
NOISE	NO / なし
EPA	YES / あり
NOTE	OIL LEAKING SLIGHTLY / オイル漏れ小

UNDERCARRIAGE

SHOE ☑ W/PAD 450 mm	TYPE	STEEL
	OK	
PIN BUSH	OK	
CARRIER ROLLER	OK	
TRACK ROLLER	OK	
FRONT IDLER	OK	
SPROCKET	OK	
NOTE		

FRONT ATTACHMENT

BOOM	TYPE	STD
	OK	
ARM	TYPE	STD
	OK	
PIPING	—	
BUCKET	TYPE	STD
	MISSING / 欠損	
BLADE	–	
PINS	BOOM	OK
	ARM	OK
	BUCKET	OK
NOTE	WITH FORK/フォーク付	

CAB/CNP

CAB/CNP	OK
ROPS	NO / なし
SEAT	OK
CONTROL LEVER	OK
A/C OR HEATER	OK
COMPUTER	OK
MONITOR	OK
BATTERY	OK
NOTE	

CYLINDERS

BOOM	MINOR OIL LEAK / オイルにじみ
SWING	–
ARM	OK
BUCKET	OK
BLADE	–
NOTE	

TURN TABLE	MINOR OIL LEAK / オイルにじみ

CONTROL

HYDRAULIC PUMP	OK
TRAVEL	OK
SWING	OK
CONTROL	OK
NOTE	

ATTACHMENT	FORK/フォーク

REMARK

SERIAL PLATE MISSING/シリアルプレート欠品

NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP / 在来船輸出の場合は要洗車

ATTENTION/注意　*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました