GREEN AUCTION

MINI EXCAVATOR

LotNo	1146021	LOCATION	KOBE-N

MAKER	MINI EXCAVATOR	YEAR	2004
MODEL	305CR	HOUR	2721
S/N	BMW01599		

☐ DOCUMENT/書類　☐ UNABLE TO TRAVEL(START)/不動車

ENGINE

MODEL	K4N
S/N	—
COOLANT	OK
OIL	OK
START	OK
BLOW-BY	NO / なし
NOISE	NO / なし
EPA	NO / なし
NOTE	

UNDERCARRIAGE

SHOE ☐ W/PAD	TYPE	STEEL
400 mm	OK	
PIN BUSH	OK	
CARRIER ROLLER	OK	
TRACK ROLLER	OK	
FRONT IDLER	OK	
SPROCKET	OK	
NOTE	RH TRACK PADS PARTIALLY INSTALLED / 右側だけ一部パッドが付いている LEFT CRAWLER SLACKNESS / 左クローラ緩み	

FRONT ATTACHMENT

BOOM	TYPE	SWING
	OK	
ARM	TYPE	STD
	CRACKED AT PIN BOSS / ピンボス割れ	
PIPING	OK	
BUCKET	TYPE	STD
	OK	
BLADE	OK	
PINS	BOOM	OK
	ARM	OK
	BUCKET	OK
NOTE	WELD REPAIR AT BOOM (ROD BRACKET) & BUCKET PIN BOSS / ブーム(ロッドブラケット)とバケットピンボス部に補修跡	

CAB/CNP

CAB/CNP	OK
ROPS	NO / なし
SEAT	OK
CONTROL LEVER	OK
A/C OR HEATER	—
COMPUTER	—
MONITOR	—
BATTERY	OK
NOTE	

CYLINDERS

BOOM	OK
SWING	OK
ARM	OK
BUCKET	OK
BLADE	OK
NOTE	

TURN TABLE	OK

CONTROL

HYDRAULIC PUMP	OK
TRAVEL	OK
SWING	OK
CONTROL	OK
NOTE	4WAY MULTI LEVER / 4WAYマルチレバー MINOR OIL LEAK FROM OIL LINE / オイルラインから少量のオイル漏れあり

ATTACHMENT	—

REMARK

RH TRACK SLOW IN FORWARD (PULLS RIGHT) / 右クローラーの前進が遅い(前進時右に寄っていく)

ATTENTION/注意　*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました